



J.O. NOËL  
HOULE &  
FILS

## Instructions for the maintenance with Rubio oil

The maintenance with Rubio oil is done in four (4) steps :

1. Clean the surface with a neutral detergent soap and let dry 8 hours. In the event that you have grain up on your counter, use 220 grit sandpaper to make a light sanding.
2. Using a brush, apply a thin layer the surface with Rubio oil. Let stand 20 minutes.
3. Using a dry, lint-free cloth, polish the surface until you have removed the excess oil and let dry for 24 hours.
4. Do not expose to water for 48 hours.
5. If necessary, repeat steps 2 and 3, as needed.

### WARNING

- Rags used for maintenance should be soaked in water before disposal because of the risk of self combustion.
- Hot containers can cause burns and delamination of the counter.
- Wet containers can cause dark circles (spots with the shape of the container). These are easy to repair ; simply repeat steps 1 to 4.
- Long-term items left on your area can create discoloration due to the fact that the oil does not filter UV rays.